

#### Particle Physics Division

### Mechanical Department Engineering Note

Number: MD-Eng-210

Date: Jan 25, 2010

Project: DECAM

Project Internal Reference: MCCDTV LN2 Cooling System

Title: DECAM MCCDTV Cryogenic Safety Review Documents

Author(s): Herman Cease

Reviewer(s): Cryogenic Safety Subcommittee

Key Words:

Abstract/Summary:

Applicable Codes: ASME DIVISION I SECTION VIII, ASME B16.5 Pipe Flanges and Flanged Fittings

#### Cryo-Review for the DECam Multi-CCD Test Vessel Closed Loop LN2 System Test in Lab A

#### System Description:

A new installation is being planned for the Dark Energy Camera project. The new installation will be used to cool the Multi-CCD test vessel (MCCDTV) using a closed loop LN2 system. The MCCDTV is currently in the Lab A control room at Sidet and is being cooled using the LN2 autofill system previously reviewed. The MCCDTV will be moved to under the dome at Lab A and will be cooled using the new LN2 closed loop cooling system. The closed loop plumbing will be attached to the vessel via a triple jacketed hose, supply, return and the vacuum jacket. The LN2 reservoir, pump, and circulation station will be outdoors just outside Lab A very near the existing 500 L dewar used on the autofill system. The new closed loop cooling system operates at 100 psig.

Once the system is operational, several phases of testing will proceed. The phases are listed.

Phase I August 2008

Located at Floor Elevation

Run Closed loop LN2 system in Lab A

Simple Heat Exchanger

Phase II August 2008

Located at 40 Foot Elevation

Run Closed loop LN2 system in Lab A

Simple Heat Exchanger

Phase III September 2008

Located at Floor Elevation

Run Closed loop LN2 system in Lab A

Heat exchanger installed in Multi-CCD Test Vessel

Phase IV Fall 2008

Located at Floor Elevation

Run Closed loop LN2 system in Lab A

Heat exchanger installed in Multi-CCD Test Vessel

MCCDTV installed in a rotation box

Phase V 2008-2009

Operate Multi-CCD Test Vessel in lab A using closed loop LN2 system

Phase VI 2009-2010

MCCDTV installed on Telescope simulator Full length of piping simulating, Vessel rotates

Operations with the new closed loop LN2 system and the MCCDTV under the dome at Lab A are expected to last until 2010.

1a. 200L Vessel Engineering Note

Pressure Vessel Enote 200L-LN2-LABA-5031 8-14-08.doc

PHPK CODE STAMP.JPG

PHPK-VacuumV note 07-1793-9911A.pdf PHPK Vacuum Vessel note

PHPK Pressure V Note 07-1793-9910.pdf PHPK Pressure Vessel note

PHPK Pressure Tests.pdf

PHPK DWG 07-1963-0500A.pdf

PHPK U1A Date Report.pdf

1b. 200L, 18 inch flange Engineering note

ENOTE-18INCH FLANGE 8-1-08.doc

18inch-flange-asme-calcs 8-1-08.xls many makes lifeties and no basis may be 1008

436426 assy.pdf

436466 RevB weldment.pdf

436552 pad9.pdf

436553 pad5 6.pdf

436554 pad8.pdf

FNAL WelderCert.pdf

1c. 200L, 18 inch flange pressure test

PRESSURE TEST PROCEDURE 200L Flange.doc

PRESSURE TEST PERMIT 200L Flange 5034.doc

PRESSURE TEST JHA 200L Flange.doc

2. Process and Instrumentation Diagram 7-31-08

Process and Instrument Diagram - ME-436389REVA

3. Instrumentation and Valve List 8-11-08

LAB A LN2TEST Valve-Instrument-List-8-11-08.xls

4. Failure Mode and Effect Analysis

DES LAB A FMEA 8 11 08.xls

5. What if Analysis

DES LAB A WHAT IF.doc

6. Operating Procedures

DECAM Lab A LN2 System Op Proceed Rev 0 8-7-08.doc

MCCOTV installed in a retation box

7. MCCDTV SiDet ODH analysis with the LN2 installation inside Lab A

SiDet ODH Analysis-3-10-08.doc

SiDet ODH Analysis-3-10-08.xls

LN2 SOURCES SIDET FACILITY.pdf bellsten VTG2014

8. FESHM 5031.1 Engineering Note for Piping Systems.

FESHM 5031.1 PIPING ENGINEERING NOTE FORM


DECAM Lab A LN2 piping Eng Note 8-11-08.doc


ASME B31.3 Radiography report


200L-LN2-LABA-trapped volume.doc

Fermi Triple Jacketed dwgs.pdf

Recommendation letter to start operations from Cryo-Review Panel 8-14-08 DECam LN2 Closed Loop Recommendation.doc








# Fermilab

•		Component <u>DES LN2 TEST</u> Location <u>LAB A</u> Date <u>7/31/08</u> By <u>Terry Tope</u>
WHAT-IF	CONSEQUENCE/HAZARD	CONCLUSION/RECOMMENDATIONS
Loss of insulating vacuums	System frosts over. Higher heat load to LN2 circuit. Potential for relief valves to open.	Safe condition. System is protected with relief valves that vent outdoors.
	May cause high consumption of liquid nitrogen.	Safe condition. Operational impact.
Loss of instrumentation	May cause system instability with respect to cryostat pressure control or regeneration heater control.	Safe condition. Operational impact.
Power outage occurs at Lab A	All control and instrumentation fails.	Safe condition. Operational impact – Historical values no longer recorded, no pressure control, no cooling flow, relief valves vent.
Leaking stem packing on a cryo valve	Gas will vent into room.	Safe condition (see ODH analysis).
Transfer line inner lines rupture, weld cracks, or silver solder joint breaks	Loss of insulating vacuum and pressurization of the vacuum space.	Safe condition. Gas will vent into room thru vacuum reliefs into room (see ODH analysis).
Weld cracks, bellows break on the vacuum circuit.	Air will fill the vacuum space, thus creating a higher heat load to the cryo circuits.	Safe condition. System is protected with vacuum relief valves.

PLC failure	Pressure control and heater control lost.	Safe condition. Operational impact. LN2 will vent
		thru relief valves.
A fire at Lab A	Fire detectors go into alarm. Sprinklers open in Lab A. Fire Department dispatched.	
	Likely equipment damage.	
	Fire or water from sprinklers could cause significant damage to controls hardware, wiring, and instrumentation.	Safe condition. Operational problem - Control system not required for system safety but required for operation.
	Superinsulation on piping and vessels could be damaged.	Safe condition. Operational problem - Heat leaks during normal operation would be unacceptable if radiation blankets are damaged.
	Heat input into cryogenic liquids builds pressure in piping and cryostat.	Safe condition. Pressure vessels and piping protected by relief valves (see relief calculations and FMEA). Relief valves vent outside.
-	Insulating vacuums may spoil if o-rings are subjected to intense heat.	Safe condition. System is protected with relief valves that vent outdoors. Operational problem - Heat leaks during normal operation would be unacceptable if insulating vacuums are spoiled.
160L stock room dewar tips over	Stock room dewar loses its insulating vacuum and vents gas	Stay clear of stock room dewar relief valve discharge
	Stock room dewar breaks open and vents liquid	If possible, use a wood board to deflect LN2 away from any carbon steel components
Bayonet or transfer line fitting is loose	System will not pressurize prior to operations.	Safe Condition. Operational problem, tighten all transfer line fittings and bayonets.



# HAZARD ANALYSIS DECAM 200L PRESSURE VESSEL PRESSURE TEST

May 12,2008 Herman Cease

#### **Description of Work:**

A pneumatic pressure test of the DECAM 200L pressure vessel will be performed using FESHM 5034. During the pneumatic test, the pressure vessel will have substantial stored energy. Safety precautions are to be taken to mitigate risks associated with the pressure test.

#### **Safety Precautions:**

The test will be performed in the gated area outdoors behind MAB. The gated area will be removed of all personnel. The supply manifold is located inside MAB with the roll up door acting as a barrier between the personnel and the vessel.

The Vessel has already been pressure tested by the manufacturing vendor, PHPK and has a documented pneumatic test pressure of 182 psig. The portion of the vessel being tested is the top flange. The top flange is naturally at a higher elevation than the testing personnel and is pointed vertically up away from all other objects.

Prior to testing, the qualified person and the section safety officer will inspect the vessel and check the test setup for safety precautions per ASME Sec. VIII, Div 1, UG-100.

On welded pressure vessels to be pneumatically tested in accordance with UG-100, the full length of the following welds shall be examined for the purpose of detecting cracks:

- (a) all welds around openings;
- (b) all attachment welds, including welds attaching nonpressure parts to pressure parts, having a throat thickness greater than 1/4 in. (6 mm).

#### HAZARDS

~ ^	
Satety Hazard	Precautions/Safety
	Procedures
	f The vessel will be filled
stored energy can cause	slowly (10% increments)
damage to equipment and	and will be checked for
personnel.	leaks at each increment. If a
	leak is found, the pressure
	is immediately reduced by
	50% per FESHM 5034
Stored Energy. Rapid release of	f All personnel will be
stored energy can cause	removed from the area of
damage to equipment and	the test. The vessel is
personnel.	located behind MAB in a
	gated area. The filling
	manifold and personnel
	will be separated from the
	vessel using the roll up
	door as a barrier.
Stored Energy. Rapid release of	The vessel was pressure
stored energy can cause	tested from the
damage to equipment and	manufacturer. This is a
personnel.	pressure test of the end
	flange mounted to the
	pressure vessel. The flange
	is at a height above
	personnel and is mounted
	vertically. The flange
	points vertically away from
	all other objects.
	Stored Energy. Rapid release of stored energy can cause damage to equipment and personnel.  Stored Energy. Rapid release of stored energy can cause damage to equipment and

	points vertically away fro all other objects.
Accepted:	Date:
Supervisor/Task Manager	



Date: May 12, 2008

#### EXHIBIT B Pressure Testing Permit\*

Type of Test:[]Hydrostatic

[X] Pneumatic

Test Pressure: 165 psig

Maximum Allowable Working Pressure: 150 psig

Items to be Tested

DECAM 200L vessel, previously pressure tested by the manufacturer

DECAM 200L Top flange.

Location of Test: Fermilab MAB

Date and Time 7/16/08

Hazards Involved

Pneumatic stored energy

Safety Precautions Taken

In addition to the items listed below, a JHA has been compiled and a testing procedure.

The test will be performed in the gated area outdoors behind MAB. The gated area will be removed of all personnel. The supply manifold is located inside MAB with the roll up door acting as a barrier between the personnel and the vessel.

The Vessel has already been pressure tested by the manufacturing vendor, PHPK and has a documented pneumatic test pressure of 182 psig. The portion of the vessel being tested is the top flange. The top flange is naturally at a higher elevation than the testing personnel and is pointed vertically up away from all other objects.

Prior to testing, the qualified person and the section safety officer will inspect the vessel and check the test setup for safety precautions per ASME Sec. VIII, Div 1, UG-100.

Special Conditions or Requirements: N/A

Qualified Person and Test Coordinator Herman Cease, PPD/Mech Dept

Date 7/16/08

Division/Section Safety Officer Wayn Sharl

Dept/Date 7/16/08

PPD/ES#

Results

No Visible leaks, Leak checked with Snoop 7/17/08 Herman Cea

Witness (Safety Officer or Designee)

Dept/Date PPD/ESH 7/16/03

\* Must be signed by division/section safety officer prior to conducting test. It is the responsibility of the test coordinator to obtain signatures.

#### DECAM 200L Pressure Vessel PRESSURE VESSEL TESTING PROCEDURE 6/16/08, H. Cease

Pressure testing the 200L Vessel for use in the Lab A Test are to follow the following procedures and guidelines. The pressure test will be a pneumatic test.

#### Overview of the testing procedure:

#### Test Setup:

The pressure test is performed using nitrogen gas obtained from nitrogen gas bottles. Approximately 1 bottle is required to fill the test vessel and achieve the full test pressure.

The supply manifold has all necessary operating valves and safety relief valves per 5034 Exhibit A. The manifold has a safety relief valve with a cracking pressure equal to 110% the MAWP of the vessel which is 150 psig \* 1.10 = 165 psig. The relief valve cracking pressure is checked prior to the pressure vessel test. Relief valve is Anderson Greenwood 83MS66-3 with a capacity of 38scfm air.

Relief valve cracking pressure 165 psig

#### **Safety Precautions:**

The test will be performed in the gated area outdoors behind MAB. The gated area will be removed of all personnel. The supply manifold is located inside MAB with the roll up door acting as a barrier between the personnel and the vessel.

The Vessel has already been pressure tested by the manufacturing vendor, PHPK and has a documented pneumatic test pressure of 182 psig. The portion of the vessel being tested is the top flange. The top flange is naturally at a higher elevation than the testing personnel and is pointed vertically up away from all other objects.

Prior to testing, the qualified person and the section safety officer will inspect the vessel and check the test setup for safety precautions per ASME Sec. VIII, Div 1, UG-100.

On welded pressure vessels to be pneumatically tested in accordance with UG-100, the full length of the following welds shall be examined for the purpose of detecting cracks:

- (a) all welds around openings;
- (b) all attachment welds, including welds attaching nonpressure parts to pressure parts, having a throat thickness greater than 1/4 in. (6 mm).

Initial Inspection Complete,		11 (	
7/16/08 Date 7/16/08	Inspector 1	Hermin Cartinspector 2 Wayne	Schnitt

#### **Starting the Pressure Test**

ASME Sec VIII Div 1 UG-100

The pressure in the vessel shall be gradually increased to not more than one-half of the test pressure. Thereafter, the test pressure shall be increased in steps of approximately one-tenth of the test pressure until the required test pressure has been reached. Then the pressure shall be reduced to a value equal to the test pressure divided by 1.1 and held for a sufficient time to permit inspection of the vessel. Inspection at the test pressure will be performed visually and using soap bubbles.

#### Pressure Steps

Step	Hold time	Comments	
82 psig	5 minutes	10:19Am	12:50
98.5 psig	5 minutes	10:29 m	1:05
115 psig	5 minutes	1034m 11085.	1:12
131.5 psig	5 minutes		1:28
150 psig	5 minutes		1:34
165psig	5 minutes		1:45
150 psig	As needed	1510518	1:50
	for inspection	ile pressure	2:10
	min hold	oray	
	30 minutes		

If a leak is detected at any pressure level reading during the test, the pressure shall be immediately reduced to one-half that pressure level reading while locating the leak.

If a leak is detected, the vessel and lines shall be depressurized before attempting any repairs or adjustments.

After inspection, the vessel shall be relieved of its pressure gradually through a valve at the test stand.

Final Inspection Complete,

7/17/08 Date Hem Castnspector 1 Jam Schullinspector 2

С	0.3					ļ
d	18.18					
S	16000					
E		joint eff				
W	69,385					
Hg		inch moment arm				
P	150	psi				
cp/se	0.002813					
1.9WHg/Sed^3	0.001776					
t	1.23					
t class 150	1.56	t - tr =	0.33			
		•				
		ID	18.18			
		OD	21			
		area of gasket		inch^2		
		load	69,385			
		compression	799.5806	psi		
		# of bolts	16			
		lbs/bolt	4336.6	lbs	5,684	psi
		nut torque	975.7	inch lbs		
			81.3	foot lbs		
		gasket load -opera		And the second consists of the second		
		Н	47858			
		Нр	21527			ļ
and the second s		W=Wml=H+Hp	69385	IDS		<u>.</u>
		В	18.180		inside diameter of t	
·		G	20.160		Diameter at gasket	reactio
		P	150		1	L
		b		effective	gasket surface seatin	g width
		<u>m</u> .	2.7			
		bo	0.705	inch		
		Appendix 2-5		mark of the tenth		
		Wm2 = bolt load to		∍t		
		Wm2=3.14*bGy	62,693		seating load ~ oper	rating lo
		У	2359	psi seatin	g stress	

Available   Segerationered   Avea available   Avea avai	Available   Estimation comment						2x ave diam	5.585	4 912	0 0 0	000	2.52	4.926	4.926	2005	2005		2.095	3.741		3.166	3.28	
Available   Painforcement	X coord         V coord         Available         resertionment         Area available         Total area           X coord         V coord         Incard         Incard         Inchr2         In							5.75	4.98	7.50	50.7	38.6	9.67	5.13	768	80%	335	2.79	6.69		4.60	5.57	
Available   Parinforcement   Parinforc	Available   Avai							9036	<b>9</b> to1	amo.	27.0	COLG	Stog	StoB	4401	4to3	4	7035	4108		3308	3406	
Available   Institution   In	X coord         Vocalitable         Particularies         Area available         Area available         Area available           X coord         Vicalitable         Inch*2         UG-35(b)(2)         UG-37.1 A(16)         UG-37.1 A(1				Total area		available	Al and Ab	·														
Available   Painforcement	Available   Avai				Area southhis	10 97 1 05	CO CONTRACTOR	7 HOU	0.00	0000	2000	300								9000			
Available   Indifficement	Acalebbe   Restrictionered   Acalebbe   Restrictionered   Acalebbe   Restrictionered   Acalebbe				Area Available	43+441+443	1	7 101										-					
Available   Interforcement   Available   Interforcement   Interforcement	Available   Avai	_			Area available	1.1G-37 1 A1/h)	CARAN!		CZO.	1,025	1025	300	200	CZU	1.025	1.025	1025			1.025			
Available   Interferoeme   Interfe	X coord         V coord         Aralabse         reinforcements controlled           X coord         Y coord         demester wall         dd         10-36/b/J2           X coord         Y coord         0.76         0.049         0.652           1 1         2.66         0.76         0.049         0.682           1 0         0.76         0.049         0.682           1 0         0.76         0.049         0.682           1 0         0.76         0.049         0.682           1 0         0.76         0.049         0.682           1 0         0.76         0.10         1.17           2 0         0.76         0.12         2.28           4 09         0.12         1.26         0.12         2.28           4 09         0.12         1.26         0.12         2.28           -3 45         0.10         1.26         0.12         2.28           -3 45         0.45         0.14         4.26         0.15           -4 56         0.5         0.10         4.26         0.10           -5 8         1.05         0.10         1.05				Area available	UG-37.1 A1(a)	inch/2		0	8	-				•		~	-					
Available   Available   Cozzle   Cozz	X coord         V coord         Inchement         Available           4 78         0.000         0.000         0.000           5.78         0.76         0.000         0.000           1 2.66         0.76         0.000         0.000           6.38         2.16         2.52         0.12           6.39         0.25         0.12         0.12           6.39         0.400         0.12         0.12           6.30         0.400         0.12         0.12           6.30         2.03         2.405         0.12           6.3         2.03         2.405         0.12           6.3         2.63         0.12         0           6.5         2.63         0.12         0           6.5         2.63         0.12         0		reinforcement	xsectionarea	pepeeu	UG-39(b)(2)	inc^2										•						
0.76 0.76 0.76 0.76 1.335 1.25 2.406 1.05 1.05	X coord   Y coord   Inches   A 78   C 18			Available	elzzon	wall												0	•	5		+	
	X coord 178 178 111 111 111 111 111 111 111 111				- 1	demeter										ľ						- 111	

				F														
Wall		ure	Long.	min (inch)	0.004	0.004	0.004	0.007	0.015	0.015		0.014	The state of the s			district designation of the second se		C. U.S.
Stress Nozzle Wall	UG-27	Internal Pressure	Circ.	t min (inch) t min (inch)	<del></del>			0.015	0.031			0.028				3		
		MAWP	Nozzle	psi	150	150	150		150	150		150						
			Inner Diam Nozzle	inch	0.662	0.662	0.662	1.117	2.28	2.28	1.25	2.098	4.25	1.05				
		nozzle	Mall	inch	0.049	0.049	0.049	0.109	0.12		0	0.154	0	0				
		opening	diameter		0.76	0.76	0.76	1.335	2.52	2.52	1.25	2.406	4.25	1.05	Asha sud			
				Y_coord	-3.26	0	2.66	0.25	-2.18	0	4.09	2.03	4.66	2.66				The second secon
					4.78	5.78	1.11	3	-6.38	9	4.09	1 .	0	6.5				The state of the s
			hole	#	•	2	3	4	5	9	7	æ	6	10				



#### **Particle Physics Division**

#### **Mechanical Department Engineering Note**

Number: MD-Eng-149 Date: March 5, 2007

**Project: DECAM** 

Project Internal Reference: LN2 Testing at Lab A

Title: Trapped Volume Relief Valve Calculations, DECam LN2 Test LabA

Author(s): Herman Cease

Reviewer(s):

**Key Words:** 

#### Abstract/Summary:

Trapped volume relief valves are sized for the DECam LN2 closed loop cooling system used for the Lab A Test. The required capacity of PRV-6202 is also calculated.

#### **Applicable Codes:**

ASME DIVISION I SECTION VIII,

CGA S-1.3 Pressure Relief Design Standards, Part 3 Stationary Storage Containers for Compressed Gasses

#### Introduction:

Trapped volume relief valves are sized for the DECam LN2 closed loop cooling system used for the Lab A Test. Trapped volume relief valves are located in any section of piping that can be isolated from the rest of the piping system. The largest isolated section of piping is the triple jacketed hose (Part #D010TVJAVCR-720). Two conditions are used to size the relief valve, loss of vacuum and exposure to fire.

The required capacity of PRV-6202 is also calculated.

#### Trapped volume relief valve

#### **CALCULATIONS**

Finding required trapped volume relief capacity using CGA section 5.2.2, pressure relief device flow capacity for loss of vacuum

$$Q_a = \frac{0.383(328 - T)}{(922 - T)} F \times G_i \times U \times A$$

$$G_{i} = \frac{73.4(1660 - T)}{C \times L} \frac{V_{g} - V_{l}}{V_{g}} \sqrt{\frac{ZT}{M}}$$

Where,

Qa = flow capacity of the relief device cubic meters per hr

F=1, correction factor

k=Cp/Cv = 0.538 BTU/Lb.R / 0.256 BTU/Lb.R = 2.1

C = 406 using Table 4 and constant k

L = 69.5 BTU/lb Latent heat at 180 Rankine

 $Vg = 1/0.22 lb/ft^3 = 4.5ft^3/lb$ 

 $VI = 1/43.1 \text{ lb.ft}^3 = 0.23 \text{ ft}^3/\text{lb}$ 

Z = 1 Compressibility factor.

T = 100K = 180 Rankine

M = 28 Molecular weight for nitrogen g/mole

U=k/l = overall heat transfer coefficient for 0.25 inch air gap

= 0.0104 BTU/hr.ft.R Air thermal conductivity / 0.02 ft insulation gap

 $= 0.52 BTU/hr.ft^2.R$ 

A = pipe total exposed surface area, from part number D010TVJAVCR-720

$$A = \pi(0.21ft) \times (65ft)$$

$$A = 43 ft^2$$

$$G_i = \frac{73.4(1660 - 180)}{406 \times 96.5} \left(\frac{4.5 - 0.23}{4.5}\right) \sqrt{\frac{1 \times 180}{28}} = 6.7$$

$$Q_a = \frac{0.383(328 - 180)}{(922 - 180)}1 \times 6.7 \times 0.52 \times 43 \, \text{ft}^2 = 11 \, \text{cfm}$$

Finding required capacity using CGA section 5.3.2, pressure relief device flow capacity under emergency conditions including fire.

$$Q_a = F \times G_u \times A^{.82}$$

Where,

Qa = flow capacity of the relief device

F=1, correction factor

Gu = 67, Cryogenic Liquid Nitrogen at (150 \*1.21)= 181 psi, Gas factor from Table 1 for unisulated container.

A = area of a 10 foot length section of pipe exposed to fire outer diameter of 2.5 inches. This is the diameter without vacuum jacket.

$$A = \pi(2.5in) \times (120in)$$
, from part number D010TVJAVCR - 720  
 $A = 942in^2 = 6.6 ft^2$   
 $Q_A = (67.0) \times (6.6 ft^2)^{82} = 315 \frac{ft^3}{\text{min}}$ 

#### **CONCLUSION**

A trapped volume relief valve with a minimum capacity of 315 cfm is required.

Circle Seal K5120B-6M-150 valve meets these requirements

PRV-6202-LN 100 PSIG Pressure Regulating Valve

The pressure regulating valve is used to set the operational condition of the vessel to 100 psig. In the event that the cryo-cooler fails or is unable to keep up with the heat load, the regulating valve opens to vent excess gas build up in the reservoir. The cryocooler capacity is 320 Watts at 80K

The pressure regulating valve is sized to vent gas generated by a 400 Watt system heat load.

Heat load = 400 J/s \* 60s/min \* 1 kJ/1000 J = 24 kJ/min Latent Heat of vaporization = 161 kJ/kg


Amount of Nitrogen Vaporized = 24 kJ/min / 161 kJ/kg = 0.15 kg/ min


Density of Nitrogen at (100 psi/ 14.7 psi ) 6.8 atmospheres =  $3.484 \text{ kg/m}^3 * 6.8 = 23.7 \text{ kg/m}^3$ 


Amount of Nitrogen Vaporized = 0.15 kg/min /  $23.7 \text{ kg/m}^3 = 6.3e-3 \text{ m}^3/\text{min} = 0.15 \text{ cfm}$ 

#### Conclusion:

A pressure regulating valve with a minimum capacity of 0.15 cfm is required to keep up with the heat load in the event that the cryo-cooler cannot.







## ITEAM Industrial Services, Inc.

## RADIOGRAPHIC INSPECTION REPORT (Gamma)

TEAM Industrial Services 3640 West 179<sup>TH</sup> Street Hammond, IN. 46323 (219) 838-0505 Fax#:-8558

For	m: 20.1 – 212, Rev 2				.,														·	
Cus	stomer: FERNI	LAB			Lo	cation:		36	40 l	W	170,14		NAMMON	٠ , 0٠		: 10	38806	54		
Spe	-15 4	E SEC I			Acı	ceptanc	e Std:		ASM	18	83	1.3	•		TEAM Procedu	re:	RT. AS	ME.I		
Rac	liation Source Type:	Source	18	CI		ective F ot Size:	ocal		. 145	*			lm to Se stance (			Exp Tim	osure ie:	9 min	!	
Pip		Plate Thickness:	N/	A	- <del></del>		eld ickne	88:	٥.	<b>६</b> ३	 + h	einf.	Join Type		80TT	Mater Type:	•	1/5		
Pen	etrameter:	7 12	Materi Type:		/s	P	enetr	amet Side	er Lo	catio			Shi Ma	m	5/ <sub>S</sub>	Shim Thick		.250"		
File	AC 1 012E)	Film "	**	File	n		34			F			010	Fili	m Technique gle ⊠ Multip		Film Pro		natio	
Ext	osure Arrangement:	<u></u>		L	ulsion	Intens	ifying	 5			<b>xp.:</b>		ront	L.,				Back	. Oh	
<u>A</u> [	B Single Wall - Panorumic	$C \square D \boxtimes B$ Sing	le Wall - O	pposite		Scree C			Wali - C			I	n Ell	ptical	(0 & 90) ar	E		gle Wall		-
4		_ //				-				\		-	- Super	* 	(0, 120, 240)	-		*	i dig	
	*			*							*		1/	• \				erublish. shoot		
								_			l			,	)←*		-	<b>↓</b>		
				/ 	281		7	<u> </u>			1.0		<u> </u>					T	<del></del>	
4				į						ation								nsity		
EXPOSURE NO.	·		- En	Repair			nojsn	Insio	noisu.	enetr		<b>?</b>	j.	<b>.</b>	<u>.</u> .			er De	oneith	
POSU	WELD NO.	VIEW	"Dn.	al or	2	F A	r Incl	en In	lete I	uste			onve	rtIfac	Ren	narks		ramer	( Pie	1
EX	4			Original	ACCEPT	REJECT	Slag or inclusion	Tungsten Inclusion	Incomplete Fusion	Inadequate Peneti	Crack	MUOL COMERNITY	Root Convexity Undercut	Film Artifact				Pnentrameter Density	3	
		, may and the second of the se		<del>                                     </del>	7		90		2		U		<b>~</b> -	žų.			······································	Z.9/4, c	-1 -	47.
ļ	W-4	0	€ ,02	9	$\mathcal{A}$											<del></del>		14.0		4.0
		12.0	l sa		$\forall$	**************************************										landa di			-	1 1 1
		240 O			$\forall$	- 1987 (A)							- A. S.							
	W-5	120		en de	7								10000			rane silan si elektri				16
		2-40		an and	7														-	
	\	1	1	-			1											T -		-
		\ /																		
	\ / =																			
											1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1									
	X		ļ												·	····	· .	-	<u> </u>	
	-/	_/\_													NATION CONTRACTOR OF THE PARTY AND ADMINISTRATION OF THE PARTY ADM			-		
	-/-	<del>/\\</del>	-		$\perp$			.**									and the second second second second		-	
	+	+									1	1						ļ		
	/ \	+			1		-					+				<del></del>		<del> </del>		$\dashv$
	<u>/</u>	<u>f</u>	PŖINT				1	L	<u> </u>	IGN.	TURE	1					· · · · · · · · · · · · · · · · · · ·	<u> </u>	<u> </u>	$\dashv$
Insp	pector: Alan		and the same of th	ar a said	٠										Le	vel:-H	I	Date: 🔀	3/. 2	تزد

## \*Industrial Services, Inc.

## RADIOGRAPHIC INSPECTION REPORT (Gamma)

TEAM Industrial Services 3640 West 179<sup>TH</sup> Street Hammond, IN. 46323 (219) 838-0505 Fax#:-8558

Forn	n: 20.1 - 212, Rev 2	() A - 1/2 -		- 1 -				t				WO No.:		· · · · · · · · · · · · · · · · · · ·	
Cus	tomer: FERMI	LAB			cation:	HAMA		2.v					103	38054	
Spe	cification:	e sec a		A	cceptance	Std:	ASN	1E 3	31.	,		TEAM Procedu	re:	LT. ASME. I	:
Rad IR-	liation Source Type: 192 🔀 Co-60	Source			ffective Foot Size:		.148"			n to Sour tance (SF)		o''	Exposu Time:	4. MIN	
Pipe Dia:	e meter: 1.5	Plate Thickness:				ickness:	.109		Reinf.	Joint Type:	8 ଧ		Material Type:	3/5	
	etrameter: ne / Size) AST	M /12	Material Type:	5/5		enetrame ource Sid	eter Loca le 🗷	ation Film Side		Shim Mat'l:			Shim Thicknes		
Tril	n ie: Kudar MX	Film Size: 45)	,, T	Film Emalsio	n#: Z:	34 60	3	Film Exp.:	1/20	) (Q   S	ilm Teo lingle <b>E</b>	hnique <i>Multipl</i>	e □ Ma	m Processing mual M Auton	natic 🔲
	osure Arrangement:				Intens	fying s (Mat'L	.}:	Pb	1	1	. OI O	Center		Back	, ଧାର
A	Single Wall - Panoramic		le Wali - Oppo		<u>C</u>	.,	e Wall - Co	ntact	D	Elliptic Superim	eal (0 &: 90 rose (0, 12	) or 0, 240)	E	Single Wall	
		1		\		1			į	*				*	
	*			*	e makes a de la companya de la compa			*		1/					
											<b>)</b> +	- *		+	
<b></b>			$\overline{}$	facta	fa the		o l	<u> </u>		Total	<u>-</u> T		1		T
NO.		Acceptance of the Control of the Con		<u>R</u> epair		lon	ion	Inadequate Penetration Crack			***************************************			Pnentrameter Density	sity
EXPOSURE NO.	WELD NO.	VIEW	l ă l	<b>a</b>		Sing or Inclusion	Incomplete Fusion	e Pe	Root Concavity	Undercut		Ren	arks	meter	Weld Density
EXPO			3	Original ACCEPT	REJECT	5	mple	ek ked	وَ اقِ	Undervut	FIRM ACTUACE			entra	Wel
		e de la companya de l		ā ĕ	Por RE	Slag		Crack Crack	20 8					i	
	W-2	0	د. ا											2.9/4.0	2.0/1.0
		120													
		240										****			
	w - 3	٥		/											<b></b>
		120		$\perp \! \! \! \! \! \! \! \! \! \! \! \! \! \! \! \! \! \! \!$	1 (A)					#*					
		240		$\perp Z$	\$ 1.00 \$										<u> </u>
	W-6	0											p-y		<u> </u>
		120		$\parallel /$									<del>, , , , , , , , , , , , , , , , , , , </del>		
		24o		$\perp \! \! \! \! \! \! \! \! \! \! \! \! \! \! \! \! \! \! \!$											<u> </u>
	W-7	0		1/									·····		
		120		$\parallel Z$		:									
		240	+	¥Z											
	<u> </u>	\/	1							44		** *			-
			-										<del></del>		<u> </u>
	X	<u> </u>									-				ļ
		//											· · · · · · · · · · · · · · · · · · ·		ļ.,
	<u> </u>	<u> </u>	PRINT					GNATURE				<u> </u>			<u> </u>
Insi	pector:			Security .			S)	ORE				La		Date: 🔼	3/-08

## TEAM Industrial Services, Inc.

## RADIOGRAPHIC INSPECTION REPORT (Gamma)

TEAM Industrial Services 3640 West 179<sup>TH</sup> Street Hammond, IN. 46323 (219) 838-0505 Fax#:-8558

	n: 26.1 – 212, Rev 2				T	anatí.	212.	3604	P4.	1 1	£-7	Sih			a		WO No	·.:	·		
	tomer: FERM	LAB					\$ <b>!</b>	A.A.				IA					TEAM			8054	angangangan sagangan damat antiropinkanka
Spe	cification:	E SEC X			A	ccept	ance	Std:		AS	ME	Ř	\$ 31				Proced	ure:		ASME. I	<u> </u>
Rad IR-	intion Source Type: 192	Source Strength:	18	CI		fecti oot Si			. 1	48				Dista	to So nce (S	SFD):	20"	Tin		9 MIM	j
Pipe	meter:	Plate Thickness:	N	Δ			Wel	id cknes	ıs:	, 11	D4 "		÷Rein	- 1 -	Joint Type		) <b>.i.i.</b>	Mate Type		5/5	
Pen	etrameter:		Materia	.1	/s	k	Pe	netra	mete		catio	n	le [	<u> </u>	Shir	n, 5	/s	Shim	kness:	, 250	•
File	1	Film . "	Type:	Fili	11						F		11/:			Film T	echnique		Film I	Processing	
	e: KOBAK MX osure Arrangement:	Size: 4.5 X	<i>1</i> 0	Em	ulsia			fying		-			1			Single		ple 🔲	Manua	al 🗷 Autor	natic 📋
4							reen	s (Ma	t'L):			<sup>2</sup> b		Fron		OFC. & 0) ptical			********	Back Single Wall	.010
4	Single Wall - Panoramic	<u>B</u> Singi	e Wall - OI	posite			<u>C</u>	Do	ubie V	Vell - C	ontact	ţ		<u>D</u>	Super	pricar(oec iempuse (0, sk	120, 240)	E		2mgie watt	
																1				*	
	*			*								*						-		1	
									\		$\mathcal{I}$									¥	
			T												35.13 15.38						<del></del>
D.				air				_		=	Insilequate Penetration									Pnentrameter Density	Å.
EXPOSURE NO.			Fn	Repair				insion	clusi	Fusio	Pener		<b>A</b>	kity		4	n.			ter D	Weld Density
oso	WELD NO.	VIEW	"UG"	l or	-	F		Inc	en Im	lete I	aate J		onca	onve	15	rtifac	Re	marks		300	l Pia
EXI				Original	ACCEPT	REJECT	Porosity	Slag or Inclusion	Tungsten Inclusion	Incomplete Fusion	adeq	Crack	Root Concavity	Root Convexity	Undercut	Film Artifact				nemt	=
				0	₹	2	Z	S	1	드	\$	Ü	122	Ř	5	E					7 () 3
	W - I	0	₹.02	٥	Ζ,														·····	2.0/4.0	2.0/2.0
		120		1	Ζ,															Contract of the Contract of th	<del>                                     </del>
		240		in the second	1																
	w - 8	٥			_															12.4	
		120			/										1 4 4 2 4 4					LLE VALUE	S. abrille
		240	-	3	/															and discontinued in the second	ļ
	\ /																		-		
											蒙							· · · · · · · · · · · · · · · · · · ·			
							1.00											***************************************			
																	·	- ngana nganganta ca			
	X	X			1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1				1 2 2												
							12.3				144.0 (1)		1 (1) (1) 1 (1) (1)								
	/ \	/ \								>											
	/	/ \																			
	/	/			·						No.	-			1		·	nany desirence de la constitue			
	المانيد	partie appropriate appropria	PRINT	4			4.				SIGN.	4TUR	E	<del></del>		·····	and the second s		agraphia.	enganizary en - gelt en marie en	with recovery and trade to the
Ins	pector:	42			ERRET.												. I	Z Level: 4	H-	Date: 7	31.08



## **DES Lab A LN2 Test Operating Procedures**

Rev	Date	Description	Originated by	Approved by
None	Aug 7, 2008	Original issue	T. Tope H. Cease	

Reviewed by: _		 
Date:		

# DES Lab A LN2 Test Operating Procedures



#### **Table of Contents**

1.0	Introduction	Ž
2.0	Flow schematic	
3.0	Required Training Prior to Operating the System	>
4.0	Fill Procedure	2
5.0	Drain Procedure	2
6.0	Heat Exchanger Cool Down Procedure	>
7.0	Liquid Circulation Start up	
8.0	Abnormal Conditions Procedures	2

Roviewed by

#### DES Lab A LN2 Test Operating Procedures

#### 1.0 Introduction

The Lab A LN2 System is used to perform preliminary tests of the cooling system and to cool the Multi-CCD Test Vessel. The MCCDTV is a prototype camera vessel for the Dark Energy Survey Camera. The LN2 reservoir and valvebox are located outside lab A. A triple jacketed hose that contains supply, return and vacuum jacket is used a transfer line from the valve box to the heat exchanger inside Lab A. The heat exchanger is a simple tube heat exchanger and is used to cool the MCCDTV.

#### 2.0 Flow Schematic

The flow schematic for the cryostat is shown in Figure 2.1. The flow schematic is also available at <a href="http://des-docdb.fnal.gov:8080/cgi-bin/ShowDocument?docid=1537">http://des-docdb.fnal.gov:8080/cgi-bin/ShowDocument?docid=1537</a> as "Process and Instrument Diagram - ME-436389REVA". Valves and instruments are referenced by number in the operating

A general overview of the Lab A LN2 Test system and funificarity with the ESHM chapters are required prior to operating the system. A general overview can be obtained with on the job training and reviewing all of the documents associated with the stytogenic safety review which can be obtained at <a href="http://des-docdb.fnal.gov/8080/egi-nn/ShowDocument?docid=153?">http://des-docdb.fnal.gov/8080/egi-nn/ShowDocument?docid=153?</a> or near the Lab A LN2 Test controls desk.

As described in FESHM 5032 "Cryogenic personnel should attend the Fermilab afety courses, "Oxygen Deficiency Hazards," "Cryogenic Safety" and "Pressurized Gas afety" or their equivalents. Other courses, as described in Chapters 4010 and 4030, may also be appropriate. General training in cryogenic principles may also be beneficial, arrucularly to personnel involved in operations."

procedures.




Figure 2.1: DECAM Lab A LN2 test flow schematic.

#### 3.0 Required Training Prior to Operating the System

A general overview of the Lab A LN2 Test system and familiarity with the FESHM chapters are required prior to operating the system. A general overview can be obtained with on the job training and reviewing all of the documents associated with the cryogenic safety review which can be obtained at <a href="http://des-docdb.fnal.gov:8080/cgi-bin/ShowDocument?docid=1537">http://des-docdb.fnal.gov:8080/cgi-bin/ShowDocument?docid=1537</a> or near the Lab A LN2 Test controls desk.

As described in FESHM 5032 "Cryogenic personnel should attend the Fermilab safety courses, "Oxygen Deficiency Hazards," "Cryogenic Safety" and "Pressurized Gas Safety" or their equivalents. Other courses, as described in Chapters 4010 and 4030, may also be appropriate. General training in cryogenic principles may also be beneficial, particularly to personnel involved in operations."

FESHM 5031, Pressure Vessels, includes a general description of what requirements are expected of a system that contains a pressure vessel. The operator should be familiar with the information contained within FESHM 5031.

FESHM 5101, Personal Protective Equipment (PPE), outlines protective equipment needed while working with cryogens. Cryogenic gloves and a full face shield shall be worn at all times while operating manual valves or working around the safety relief devices. Long pants and closed toe shoes are recommended while working with cryogenics.

Before any of the following procedures are performed, get training from a person experienced with the complete system.

#### 4.0 Fill Procedure

The 200L Vessel is filled using 160L portable dewars. Station the 160L dewar near the fill line on the 200L vessel. The first time the 200L vessel is filled, two 160L dewars are needed to completely fill the system.

Prior to performing a fill,

Don face shield, and cryogenic gloves.

Check that the 160L fill dewar is pressurized above 200psig,

Attach an all metal transfer line with the proper flare fittings, and have wrenches available to tighten the fittings.

- 1) Open fill valve MV-6204
- 2) Open Fill try-cock valve MV-6208
- 3) Slowly open the valve on the 160L dewar to start transferring liquid into the 200L vessel Note: The 200L is full when liquid vents from the fill try-cock valve.
- 4) Slowly close the valve on the 160L dewar.
- 5) Close fill valve MV-6204.
- 6) Close fill try-cock valve MV-6208.
- 7) Wait a few minutes, using the wrenches slowly open the flare fittings and remove the transfer line.

#### 5.0 Drain Procedure

When the cooling system is stopped, most of the liquid drains back into the 200L vessel. If maintenance is needed on the vessel, the liquid is drained from the system.

Prior to draining the dewar, don face shield, cryogenic gloves. The fog produced when venting the vessel is extremely cold and creates a low oxygen pressure area. Ensure that this operation takes place slow enough that a hazard is not created.

- 1) Slowly open the fill try-cock valve MV-6208 to vent excess pressure from the 200L vessel.
- 2) Slowly open valve MV-6205 and let the liquid vent from the vessel. MV-6208 is also used to control the pressure in the dewar and the venting rate.
- 3) When all of the liquid has been vented, close valves MV-6205 and MV-6208.

# 6.0 Heat Exchanger Cool Down Procedure

This procedure is used to cool down all of the piping in the system prior to operations. The 200L vessel is pressurized, liquid from the vessel is then pushed thru the piping system. The boil-off gas is vented using MV-6307. Prior to operating manual valves, don face shield, and cryogenic gloves.

- 1) Close valves MV-6307, 6208, 6205, 6204, 6310, 6302, 6303.
- 2) Open valves MV-6216, 6201.
- 3) Let the system pressurize to the normal operating pressure, pressure can be built up using heater 6102 and setting the set-point on TE-6211 to 100K.
- 4) Slowly Open return line vent valve MV-6307 and allow the piping system to cool down. Approximately 20 Liters are needed to boil-off to cool all of the piping down.
- 5) Once the system is cold, slowly open MV-6303 and close MV-6307

## 7.0 Liquid Circulation Start up

Liquid circulation can start up once the system has been pressurized and cooled down. The pump is initially started by circulating all of the liquid thru the bypass valve MV-6310. Once the pressure stabilizes in the 200L vessel then liquid can slowly be circulated through the rest of the piping system until full design flow is achieved. The heater in the heat exchanger is not used until the full design flow is achieved. Prior to operating manual valves, don face shield, and cryogenic gloves.

- Pressurize the system and cool down all of the piping using the Cool Down Procedure.
- 2) Close valves MV-6302, 6307, Valve MV-6303 is left open ¼ turn so that a trapped volume in the piping system is not created
- 3) Open control valve MV-6310 half way
- 4) Slowly start pump 6103, increase speed until design flow rate is achieved. Confirm flow rate using PDI-6313 and the pump flow curve.
- 5) Slowly open valve MV-6302
- 6) Once the pressure in the vessel has stabilized, slowly open valve MV-6303
- 7) Adjust flow rate to the design flow rate using control valve MV-6310 and confirming the flow rate using FT-6301 and PDI-6313.
- 8) Once the flow rate and pressure in the vessel are stable, the heat exchanger can be operated.

### 8.0 Abnormal Conditions Procedures

Small leak, Alert other people, Evacuate area,
Large Leak, Alert other people, Evacuate area, call safety -3131
Dewar failure, Alert other people, Evacuate area, call safety -3131



# DES Lab A LN2 Test Piping System Engineering Note

Rev	Date	Description	Originated by	Approved by
None	Aug 11, 2008	Original issue	T. Tope H. Cease	

Reviewed by:	
Date:	

# DES Lab A LN2 Test Piping System Engineering Note

# **Table of Contents**

1.0	Introduction	2
2.0	Flow schematic	٠٠٠٠٠٠٠٠٠٠٠٠٠٠٠٠٠٠٠٠٠٠٠٠٠٠٠٠٠٠٠٠٠٠٠٠٠٠
3.0	Design codes and evaluation criteria	······
4.0	Materials	·······
5.0	Piping design and analysis	5
6.0	Pressure relief system	17
7.0	Welding and inspection	17
8.0	Pressure testing	17
9.0	Appendix	17

# DES Lab A LN2 Test Piping System Engineering Note

## Introduction

This document constitutes the Piping System Engineering Note for the cryogenic piping associated with the DES Lab A LN2 test.

The pipe descriptions and a table summary of the operating parameters are shown in Table 1.1.


Table 1.1: Cryogenic piping description and summary								
Description	Fluid	OD (in)	ID (in)	P <sub>operatin</sub> g (psid)	P <sub>max</sub> (psid)	Temp (K)		
U-tube LN2 piping 1 in. SCH 40 pipe (vacuum jacketed)	LN2	1.315	1.049	115	165	100		
Drain Line, Fill Trycock Line, and Fill Line for the DES pressure vessel 3/4 in. OD tube	LN2	0.750	0.652	100	150	100		
Vent line	GN2	0.250	0.180	100	150	> 100		
Cooling Ring 3/4 in. SCH 10 pipe	LN2	1.050	0.884	100	150	100		
Cooling Ring ¾ in. OD tube	LN2	0.7500	0.666	100	150	100		
Valve Box (numerous components)	LN2	*	**	100	150	100		

<sup>\*</sup>The largest diameter piece of piping in the valve box is 1 inch pipe.

<sup>\*\*</sup>The thinnest pipe wall thickness in the valve box is 0.065 inches.

## 2.0 Flow schematic and galeronignal makes galgital

The flow schematic for the cryostat is shown in Figure 2.1. The flow schematic is also available at <a href="http://des-docdb.fnal.gov:8080/cgi-bin/ShowDocument?docid=1537">http://des-docdb.fnal.gov:8080/cgi-bin/ShowDocument?docid=1537</a> as "Process and Instrument Diagram - ME-436389REVA".



A schematic of the piping layout at Lab A is shown in figure 2.2 The 200L vessel, instrument lines, all relief valves, and the valve box are located outside at Lab A. The triple jacket hose is used as a transfer line to the camera heat exchanger which is located inside Lab A under the dome.




Figure 2.2: DECAM Lab A LN2 test piping schematic.

## 3.0 Design codes and evaluation criteria

The DES Lab A LN2 Test piping must meet all of the requirements of Section 5031.1 of the Fermilab ES&H Manual. This section states that piping systems containing cryogenic fluids fall under the category of Normal Fluid Service and shall adhere to the requirements of the ASME Process Piping Code B31.3.

#### 4.0 Materials

The piping is fabricated from 304/304L and 316/316L stainless steel tube and pipe. The allowable stress used in this document is 16,700 psi, which is the lowest value listed for these pipe and tube materials in B31.3 Appendix A.

The LN2 piping will be operated at 100 K. This is above the minimum temperature listed for 304/316 stainless steel pipe or tube (19 K). According to Table 323.2.2 of the Code, impact testing is not required for these austenitic stainless steels. However, Table 323.2.2 does require impact testing of the weld metal and heat affected zone. Except as stated in Table 323.2.2 Note (6) where impact testing is not required when the minimum obtainable Charpy specimen has a width along the notch of less than 2.5 mm (0.098 in). The 1 inch SCH 40 piping that comprises the inner line of the U-tube assembly has a wall thickness of 0.133 inches and is the only piping in the system with a wall thickness greater than 0.098 in. See section 7.0 for comments with respect to impact testing.

## 5.0 Piping design and analysis

A schematic of the piping attached to the vessel is shown in Figure 5.1. The valve box piping that attaches to the vessel is shown in Figure 5.2. A flexible vacuum jacketed hose connects the cooling ring shown in Figure 5.3 to the valve box piping.




Figure 5.1: Piping attached to the vessel.



Figure 5.2: Valve box piping (contained in a foam box).




Figure 5.3: Cooling Ring piping.

The minimum thickness of the pipes is evaluated using the procedures in 304.1.2(a) of ASME B31.3. The minimum tube thickness for seamless or longitudinally welded piping for t<D/6 is given by:

$$t = \frac{PD}{2(SEW + PY)}$$

where: t = wall thickness, (t mfg is the manufacturers minimum wall thickness while t req'd is the thickness required by the above equation)

P = internal design pressure

D = outside diameter (manufacturers nominal value is used)

S = allowable stress from table A-1

E = quality factor from table A-1A or A-1B = 0.8 (worst case)

W = weld joint strength reduction factor = 1

Y = coefficient from Table 304.1.1 = 0.4

Table 5.1 summarizes the results of the wall thickness calculation.

Т	able 5.1.	Cryoge	nic piping	g param	eters		
Pipe / Tube	P (psid)	D (in)	S (psi)	E	t req'd (in)	t mfg min (in)	MAWP (psid)
U-tube LN2 piping	165	1.315	16,700	0.8	0.007	0.116	3,037
Drain Line, Fill Trycock Line, and Fill Line for the DES pressure vessel	150	0.750	16,700	0.8	0.004	0.044	1,645
Vent Line	150	0.250	16,700	0.8	0.001	0.0315	3,744
Cooling Loop	150	1.050	16,700	0.8	0.006	0.0726	1,956
Cooling Loop	150	0.750	16,700	0.8	0.004	0.0378	1,403
Valve box (worst case OD and wall THK)	150	1.315	16,700	0.8	0.007	0.065	1,375

In the above six cases the manufacturer's minimum wall thickness of the piping is greater than the minimum thickness required by ASME B31.3.

The "unlisted components" installed in the piping system as defined in B31.3 Section 304.7.2 are shown in Table 5.2.

	Table 5.2. Unliste	d piping co	mponents.	
Component	Source	Pressure rating [psig]	System Design Pressure (psig)	Comment
Vacuum jacketed flex hose	Duraflex part # D010TVJAVCR- 720	150 <sup>(a)</sup>	150	40-40 Ta Ca
Bayonet	PHPK, part # PBA-10	150 <sup>(b)</sup>	150	
See th	e valve and instrume	ent list for o	ther componen	ts.

- (a) http://dcs-docdb.fnal.gov:8080/cgi-bin/RetrieveFile?docid=1537&version=6&filename=Fermi\_Triple\_Jacketed\_wgs.pdf
- (b) PHPK literature states that "All bayonets have been computer analyzed to meet the ANSI/ASME B31.3 piping code requirements...".

The flexibility of the U-tube piping was analyzed using ANSYS. The model boundary conditions and results are summarized in Figures 5.2 and 5.3.

The thermal shrinkage was taken to be  $321 \times 10^{-5} \Delta L/L$  for 304/316 Stainless (B31.3 Table C-1). The modulus of elasticity of 304 Stainless was input as  $30.3 \times 10^6$  psi (B31. Table C-6) along with a Poisson's Ratio of 0.30 (B31.3 para 319.3.3).

The model is comprised of ANSYS PIPE 16 (straight), and PIPE 18 (elbow) elements in which ANSYS calculates flexibility and stress intensification per B31.1. The stress intensification factors for B31.3 are the same as for B31.1.

As a check of the FEA model, a simple model consisting of a section of straight pipe was analyzed. The pipe was anchored at both ends and cooled from room temperature to liquid nitrogen temperature. The stress reported by the FEA model matched the result obtained by multiplying the unit thermal strain by the modulus of elasticity.

Per B31.3 Appendix P, the operating stress is computed using equation (P17a)

$$S_o = \sqrt{(S_a + S_b)^2 + 4S_t^2}$$

where the axial  $(S_a)$ , bending  $(S_b)$ , and torsional  $(S_t)$  stresses are combined and compared to the allowable stress  $S_{oA}$  in para. P302.3.5(d) where

$$S_{oA} = 1.25 f(S_c + S_h)$$
.

 $S_c$  is the basic allowable stress at the minimum metal temperature expected during the displacement cycle under analysis and  $S_h$  is the basic allowable stress at the maximum metal temperature expected during the displacement cycle under analysis. Both  $S_c$  and  $S_h$  were taken to be 16,700 psi. The stress reduction factor f was taken to be 1.0 because this system will see less than 1,000 cycles in its lifetime.

$$S_{a4} = 1.25 \times 1.0 \times (16,700 + 16,700) = 41,750 \, psi$$

A macro (available in the appendix) was used to retrieve  $S_a$ ,  $S_b$ , and  $S_t$  from ANSYS and then compute the combined stress. The peak operating stress for the Supply U-tube was found to be 5,280 psi for the cold case (thermal shrinkage + 165 psid) and 295 psi for the warm case (165 psid loading only). The peak operating stress for the Return U-tube was found to be 6,826 psi for the cold case (thermal shrinkage + 165 psid) and 295 psi for the warm case (165 psid loading only).

Thus the operating stress range for both U-tubes is only a few thousand psi and does not exceed the allowable operating stress limit. These stresses are well below the 16,700 psi limit for the U-tube piping components.

The Fill, Drain, and Trycock lines were also analyzed using an FEA model to investigate the thermal stress. In the FEA model these lines were modeled as fixed to their respective VCR fittings on the top flange and to a clamp attached to the Unistrut frame (see Figure 5.1). Figures 5.4 thru 5.6 show the model results. Application of B31.3 equation P17a resulted in a peak stress of 6,254 psi for the Fill Line, 8,353 psi for the Drain Line, and 7,770 psi for the Fill Trycock line. Thus the stress in each line due to thermal shrinkage and internal pressure is less than the 16,700 psi allowable.




Figure 5.2: Supply U-tube FEA model boundary conditions and results.




Figure 5.3: Return U-tube FEA model.




Figure 5.4: Fill line FEA model boundary conditions and results.




Figure 5.5: Drain line FEA model boundary conditions and results.




Figure 5.6: Fill trycock FEA model boundary conditions and results.

The Cooling Ring piping bends (Figure 5.3) are analyzed per para. 304.2.1 of the Code. The minimum required thickness is given by:

$$t = \frac{PD}{2((SEW/I) + PY)}$$

where: t = wall thickness

P = internal design pressure, 150 psid

D = outside diameter, 1.050 in.

S = allowable stress from table A-1, 16,700 psi for 304 S.S.

E = quality factor from table A-1A or A-1B = 0.8 (worst case)

W = weld joint strength reduction factor = 1

Y = coefficient from Table 304.1.1 = 0.4

I = factor for location in pipe bend: intrados, extrados and centerline

The following equations are used to determine I at the three locations:

at the intrados:

$$I = \frac{4(R_1/D) - 1}{4(R_1/D) - 2}$$

at the extrados:

$$I = \frac{4(R_1/D) + 1}{4(R_1/D) + 2}$$

at the centerline:

$$I = 1.0$$

 $R_I$  = bend radius of the tubing, 8.225 in.

The results are as follows:

t(in) for 8.225 in. radius: at intrados = 0.0061; extrados = 0.0057; centerline = 0.0059 (same as straight tube)

The bent pipe has a minimum wall thickness of 0.0726 inches so this requirement is satisfied.

## 6.0 Pressure relief system

Table 6.1: DES Lab A LN2 Test relief settings.						
Circuit	Design pressure	Relief setting	Relief valve ID			
Drain line	150 psid	150 psig	SV-6213			
Fill trycock line	150 psid	150 psig	SV-6213			
Fill line	150 psid	150 psig	SV-6200-LN, SV-6213			
Return U-tube	165 psid	150 psig	SV-6213			
Supply U-tube	165 psid	150 psig	SV-6213			

## 7.0 Welding and inspection

According to B31.3 Section 341, all piping in Normal Fluid Service shall be examined. All welding was performed by Lenny Harbacek whose stainless steel qualification is included in the Appendix. Eight butt welds were radiographed and the results are available as an attachement. The system contains 70 butt welds.

by impact tests of the weld metal and heat affected zone for wall thicknesses greater than 0.098 inch when used at liquid nitrogen temperatures. The 1" SCH 40 U-tube piping has a wall thickness of 0.133 inches. Fermilab does not have a qualified welding procedure for use of austenitic stainless steels at liquid nitrogen temperatures. However, the stress in this piping is far below the allowable stress. Low stress reduces the likelihood of brittle failure in the heat affected area. The ASME pressure vessel code recognizes the suitability of 304/304L & 316/316L for use at liquid nitrogen temperatures. In Section VIII Division 1, paragraph UHA-51(d)(1) exempts 304/304L and 316/316L from impact testing for both the base metals and the heat affected zones.

# 8.0 Pressure testing

The piping system will be pressure tested in accordance with Section 5034 of the Fermilab ES&H Manual and 345.5 of the Code. The test pressure is 110% of the design pressure which is  $1.1 \times 150 = 165$  psig.

# 9.0 Appendix

```
post.dat
/post1
/sys, del results.res
esel,s,ename,,16
etab,sa,smisc,13
etab,sb,nmisc,90
etab,st,smisc,14
esel,s,ename,,17
etab,sa,smisc,37
etab,sb,nmisc,268
etab,st,smisc,38
esel,s,ename.,18
etab, sa, smisc, 13
etab, sb, nmisc, 91
etab, st, smisc, 14
allsel
*get,ecnt,elem,,count ! number of elements selected
*do,qq,1,ecnt ! loop through the elements
*do,qq,1,ecnt
/gopr
*get,el,elem,,num,min
                                   ! get starting element, lowest number
*get,ssa,e]em,el,etab,sa
*get,ssb,elem,e1,etab,sb
*get,sst,elem,e1,etab,st
```

/out,results,res,,append
res\_%e1%=sqrt((abs(ssa)+ssb)\*\*2+4\*sst\*\*2)
/out

esel,u,elem,,el \*enddo

Page 1

Figure A-1: ANSYS macro used to compute operating stress.

# COPY

# **FERMILAB**

## **Weider Qualification Test Record**

Welder's Name_	Leonard Ha	<u>rbacek</u> Ident No	122261 Date <u>03/19/99</u>
Welding Process	GTAW	Type	Manual
Test in Accordance	e With WP	S # ES-155003	Root Open
Material Specifica	ntion <u>SA 53</u>	-B To Mate	erial Specification SA 53-B
P-No_1To	P-No <u>1</u>	Thickness <u>,280</u>	" Diam <u>6"</u>
Filler Metal Speci	fication SFA	A5.18 Classifica	ation <u>ER-70S-2</u> F-No 6
Thickness Depos	ited	.280	- The second
Backing Arg	on	Gas Shiek	ding Argon
Position 6	⊱G	Progression_	Upward
Electrical Charact	eristics:	CurrentD	C Polarity Straight
Thickness Qualific	ed <u>.560</u>	"Max Diameter C	Qualified 2-7/8" O.D. and over
	Gl	UIDED BEND TEST	RESULTS
Specimen No	Туре	Figure	Results
1	Face	QW-462.3a	Acceptable
2	Face	QW-462.3a	Acceptable
3 4	Root	QW-462.3a	Acceptable
4	Root	QW-462.3a	Acceptable
Test Conducted B	y IFR Engi	neering Test No	008-09-01 Date 3/19/99
We certify that the prepared, welded ASME Code.	e statement and tested	s in this record are in accordance with t	correct and that the test welds were the requirements of Section IX of the
Ву:	Ellelle	- the state of the	,
Date: <u>4/92/</u>	99	<del></del>	

Figure A-2: Leonard Harbacek's welding qualification for stainless steel.



To:

Greg Bock

Particle Physics Division

From:

Phil Pfund

Chair, Village & Misc. Cryogenic Safety Review Panel

Subject: DECam LN2 Closed Loop Safety Review

Dear Greg,

The Village & Misc. Cryogenic Safety Review Panel has completed its review of the DECam LN2 Closed Loop design and installation in Lab A.

#### Our review consisted of:

- Review of safety related documentation for the LN2 loop. All of the DECam LN2 documentation and updates are maintained by Herman Cease at: <a href="http://des-docdb.fnal.gov:8080/cgi-bin/ShowDocument?docid=1537">http://des-docdb.fnal.gov:8080/cgi-bin/ShowDocument?docid=1537</a> login: desreviews, password: DESrev The documentation related to the closed loop is collected by subject area and consists of:
  - Document List
  - o (1a) 200L vessel engineering note and supporting documents
  - o (1b) 200L 18 inch flange engineering note and supporting documents
  - o (1c) 200L 18 inch flange pressure test and supporting documents
  - o (2) Process and instrumentation diagram, 7/31/08
  - o (3) Instrumentation and valve list, 8/11/08
  - o (4) Failure Mode and Effect analysis, 8/11/08
  - o (5) What-if analysis
  - o (6) Operating procedures
  - o (7) SiDet ODH analysis and supporting documents
  - o (8) Piping system engineering note and supporting documents
- Individual panel member telephone and e-mail exchanges with Herman Cease from initiation of the review on 1/25/08 through 8/14/08 resulting in revisions to the documentation listed above.
- 2/1/08 visit to Lab A by panel members to view the planned installation location and to discuss design and pending documentation with Herman Cease.
- 5/5/08 meeting with Herman Cease to discuss status of the design and documentation.
- 8/6/08 visit to Lab A by panel members to view status of the installation and to discuss comments to documentation with Herman Cease.
- 8/14/08 visit to Lab A by panel members to view the final installation.

Based on the above listed review activities, we are satisfied that the DECam LN2 closed loop in Lab A as designed and installed can be operated safely. We recommend that you authorize the operation.

Regards,

Phil Pfund

On behalf of the Village & Misc. Cryogenic Safety Review Panel

Copy:

Wayne Schmitt

Herman Cease

Panel Members (Brian DeGraff, Tom Page, Dave Pushka)

Arkadiy Klebaner

OK - Under most circumstances PI-6209 provides a redundant reading

OK - PT-6215 provides a redundant reading

FM	<u>EA</u>						
	<del>o 8-11</del>			Failure or Error Mode	Hazard or Effect	Hazard Class	Demorks
Type Check			Service	Pasure of Effor mode	Mazard or Effect	HOZELU CHISS	Connects
cv	6312	Γ	Check valve supply line	Fails open	Pump damage	Safe	Operational problem - Liquid draining back while pump is off could over-speed the impeller. Thermal tests cannot be conducted if the pump is damaged.
cv	6312	LN2	Check valve supply line	Fails closed	Pump dead heads	Safe	Operational problem - Lack of flow would be indicated by FT-6301, pump could eventually cavitate due to heat input into static liquid. There is a very low probability that the "swing" style check valve could be completely blocked.
	L	<b></b>					
Filter						Safe	OK - Small possibility particulate matter could stop PRV-6202 from
F	6217	LN2	Instrument line filter	Fails open	Normal		sealing leading to excessive GN2 venting.  Operational problem - can't measure vent rate which helps
F	6217	LN2	Instrument line filter	Fails closed (plugged)	instrument line vent is closed	Safe	understand the thermal tests.
Flow in	netrum	ants.					
FI	6201	LN2	Instrument line flow indicator Instrument line flow indicator	Incorrect reading high Incorrect reading low	incorrect flow incorrect flow	Safe Safe	Operational problem -Heat leak calculations may be inaccurate.  Operational problem -Heat leak calculations may be inaccurate.
FT	6301	LN2	Supply line flow transmitter	Incorrect reading high Incorrect reading low	incorrect flow incorrect flow	Safe Safe	Operational problem -Heat leak calculations may be inaccurate.  Operational problem -Heat leak calculations may be inaccurate.
[ +1	[6301]	LNZ	Supply line flow transmitter	macorect reading row	niconder now		
Heatin	g elem	onts		OFF	Loss of vapor pressure	Safe	Operational problem - Without the heater to balance the cryocooler the system will depressurize and the cooling loop performance degrades due to increased bubble size in the pumped loop. Thermal tests cannot be conducted without the heater.
HTR	6102	LN2	Heater inside reservoir	ON	Heater assembly overheats	Safe	Operational problem - PLC will shull off heater based on TE-6211. It PLC fails, hardware thermal switch set at 55 C will cut AC power to heater. Thermal tests cannot be conducted with a run away heater
				ON .	LN2 vaporized	Safe	Operational problem - SV-6213 has enough capacity for LN2 vaporized by the heater. Thermal tests cannot be conducted with a runaway heater.
		Π		OFF	Can't test system performance	Safe	Operational problem - Can't perform thermal tests without HTR-640: which simulates experimenter hardware heat dissipation.
нтя	6405	LN2	Trim heater on Heat exchanger	ON	Heater assembly overheats	Safe	Operational problem - PLC will shut off heater based on TE-6404. It PLC fails, hardware thermal switch set at 55 C will cut AC power. Can't conduct thermal tests with a runaway heater.
				ON	LN2 vaporized	Safe	Operational problem - SV-6213 has enough capacity for LN2 vaporized by the heater. Thermal tests cannot be conducted with a runaway heater.
Liquid	i level :	traosu	sitters ·				
LT	6207	LN2	Level Transmitter	Incorrect reading high	Pump could cavitate	Safe	Operational problem - PDI-6313 also provides level information. If the pump is run without enough NPSH, it may be damaged.
LT	6207	LN2	Level Transmitter	incorrect reading low	No Hazard	Safe	Operational problem - Indication of low liquid level is redundant with PDI-6313
Manua	al valv						
	ni valve	T	La	Fails open	No Hazard	Safe	OK - normal position
MV	6201	LNZ	Instrument Line Isolation valve on flow meter 6201	rais oper	140 FMZZEIU	Outo	Operational problem - SV-6218 can vent flow from supply dewar. F
MV	6201 6204	<del> </del>	Instrument Line Isolation valve on flow meter 6201	Fails closed	Instrument line vent is closed  Vessel empties	Safe Safe	Operational problem - Vapor pressure pushes LN2 out of vessel an onto ground outside of Lab A if supply devar is not attached.
1916	0204	1.02	I'M rust,	· · · · · · · · · · · · · · · · · · ·	Toost diputs		Thermal tests cannot be conducted.  Operational problem - If a dewar is attached, SV-6200 provides a
MV	6204	├	Fill Port,	Fails closed	Can't fill vessel	Safe	trapped volume relief. Can't fill system and conduct thermal tests if MV-6204 is closed.  Operational problem - Vapor pressure pushes LN2 out of vessel and
MV	6205	LN2	Drain Port, Manual Shutoff Valve	Fails open	Vessel empties	Safe	onto ground outside of Lab A. Can't conduct thermal tests without LN2.
MV	6205	LN2	Drain Port, Manual Shutoff Valve	Fails closed	Can't empty vessel	Safe	OK - Dewar could be emptied thru MV-8204 if MV-6205 is closed.
MV	6208	LN2	Full Try Cock, Manual valve	Fails open	Dewar blows down	Safe	Operational problem - Need ~ 100 psig of pressure for pressure drop to be tolerable in pumped lines. < 100 psig may lead to inadequate cooling and the thermal tests will fail.  Operational problem - PDI-6313 and LT-6207 also provide level
MV	6208	LN2	Full Try Cock, Manual valve	Fails closed	Over fill vessel	Safe	indication. If vessel is overfilled SV-6231 can handle the excess liquid. Pressure control will be difficult if vessel is too full due to small vapor volume and high heat leak.
MV	6216	LN2	Instrument Line Isolation valve	Fails open	Cannot isolate instrument line	Safe	Maintenance problem - If pressure gauge, pressure transmitter, or back pressure regulator fail, system will have to be blown down for repair. Thermal tests will have to stop.
MV	6216	LN2	Instrument Line Isolation valve	Fails closed	isolates pressure gages and regulator valve	Safe	Operational problem - no pressure indication. PI-6206 could be used to measure the vapor pressure + liquid head.
MV	6302	LN2	LN2 dewar pump outlet isolation	Fails open	Can't isolate pump discharge	Safe	Operational problem - Can't isolate pump from flexible hose and cooling ring to examine cryostat only heat leak or perform maintenance on these parts.
MV	6302	LN2	LN2 dewar pump outlet isolation	Fails closed	Can't pump liquid to cooling ring	Safe	Operational problem - Can't perform thermal tests. Potential trappe volume or pump dead head relieved by SV-6311.
MV	6303	LN2	Return Line, Manual valve near reservoir	Fails open	Can't isolate pump supply	Safe	Operational problem - Can't isolate pump from flexible hose and cooling ring to examine cryostat only heat leak or perform maintenance on these parts.
MV	6303	-	Return Line, Manual valve near reservoir	Fails closed	Can't pump liquid to cooling ring	Safe	Operational problem - Can't perform thermal tests. Potential trappe volume or pump dead head relieved by SV-6304.  Operational problem - Resid will be numbed out of MV-6307 and
MV	6307	LN2	Return Line port	Fails open	Liquid is pumped out of system	Safe	Operational problem - liquid will be pumped out of MV-6307 and onto the ground outside of Lab A. Thermal tests will be disrupted.
MV	6307	├	Return Line port	Fails closed	Can't cool down piping according to procedure	Safe	Operational problem - can't cool down piping according to procedures. Thermal tests will not be started until valve is fixed.  Operational problem - flow to cooling ring will be inadequate and
MV	6310	╫	Manual Control Valve, bypass near reservoir	Fails open	Very little flow to cooling ring	Safe	cooling tests can't be conducted.  Operational problem - pump may operate at an undesirable point or
MV	6310	LN2	Manual Control Valve, bypass near reservoir	Fails closed	All pump flow goes thru cooling ring	Safe	the pump curve and provide poor cooling to the cooling ring. Syste and thermal tests can't be performed.
Press	ure ind	dicatin	g gauges			····	<b>.</b>
PDI	6313	LN2	Differential pressure indicator, supply return	Incorrect reading high	Pump could cavitate	Safe	Operational problem - LT-6207 also provides level information. Indication of high liquid level must be investigated.
PDI	6313	LN2	Differential pressure indicator, supply return	Incorrect reading low	No Hazard	Safe	Operational problem - indication of low liquid level must be investigated.
PE	6101	v	Pressure element for reading the vacuum pressure	Incorrect reading - low	Insulating vacuum worse than indicated	Safe	Operational problem - heat input could exceed cryocooler capacity and system would start venting which could disrupt the thermal test
PE	6101	v	Pressure element for reading the vacuum pressure	Incorrect reading - high	insulating vacuum better than indicated	Safe	Operational problem - time could be spent investigating a non-existent problem.
P)	6206	ŁN2	Drain Port, Pressure Indicator	Incorrect reading - low	No Hazard	Safe	OK - Under most circumstances PI-8209 provides a redundant reading
PI	6206	LND	Prain Port Pressure indicator	Incorrect reading - high	No Harard	Safe	OK - Under most circumstances PI-6209 provides a redundant

No Hazard

No Hazard

Incorrect reading - high

Incorrect reading - low

Safe

PI 6206 LN2 Drain Port, Pressure indicator

PI 6209 N2 Vessel Pressure Indicator

					No Manuel	Safe (	OK - PT-6215 provides a redundant reading
6209	N		ssel Pressure Indicator	incorrect reading - high	No Hazard		OK- Reduntant with PI-6209
6305	5 LF	12 Su	pply line pressure indicator near reservoir	Incorrect reading - low	No Hazard		OK- Redundant with PI-6209
6305	5 U	12 Su	pply line pressure indicator near reservoir	Incorrect reading - high	No Hazard		
6401	+		pply line, Pressure indicator near heat exchanger	incorrect reading - low	No Hazard		OK- Reduntant with PI-6202
6401	+-		pply line, Pressure indicator near heat exchanger	Incorrect reading - high	No Hazard		OK - Reduntant with PI- 6202
	+-			Incorrect reading - low	No Hazard	Safe	OK -Reduntant with PI-6201
6402	2 11		turn line, Pressure indicator near heat exchanger	Incorrect reading - high	No Hazard	Safe	OK - Reduntant with PI-8201
6402	2 LI	V2 Re	turn line, Pressure indicator near heat exchanger	incorrect reading - riigit	107 1001		
SUFO FO	eguis	tors				Т	Operational problem - Can't perform cooling tests if system lose:
V 6202			strument Line, Boil-Off Regulator	Fails open	Dewar blows down	Sale [	pressure. Operational problem - SV-6213 will vent excess pressure if
ev 6202	2 N	12 in	strument Line, Boil-Off Regulator	Falls closed	Dewar pressure builds	Safe	cryocooler cannot keep up with heat leak. Heat leak cannot be measured thru FI-6201.
esure tr	ransa	mitter				Codo	OK - PI-6209 provides a redundent reading
T 621			essure Transmitter, Vessel pressure	Incorrect reading -low	No Hazard		OK - PI-6209 provides a redundant reading
T 621		12 P	essure Transmitter, Vessel pressure	Incorrect reading - high	No Hazard	Safe	ОК-7-0209 розгост 5
nps				TT	Damage to pump	Safe	Operational problem - Can't provide LN2 to cooling ring. Cooling
mp   610	13	12 S	ubmersible LN2 pump	Cavitales		Code	tests cannot be performed.  Operational problem - Can't provide LN2 to cooling ring. Cooling
np 610	13 1	V2 S	ubmersible LN2 pump	Fails off	No Hazard	Safe	tests cannot be performed.  OK - power can be removed at local fuse panel if required.
mp 610	23	N2 S	ubmersible LN2 pump	Fails On	No Hazard	Safe	Overpressurization from a runaway pump speed is releived throu SV-6213
				1			
oture di				5.00	No Haverd	Safe	OK - Dewar will vent thru SV-6213 if necessary
0 621	14 1	N2 F	eservoir Positive pressure 2nd main relief	Fails closed	No Hazard		Operational problem - System will depressurize and cooling test
D 621	14 1	N2 F	eservoir Positive pressure 2nd main relief	Fails open	No Hazard	Safe	cannot be performed.
iable si				Fails off or too slow	No Hazard	Safe	Operational problem - Can't provide LN2 to cooling ring. Coolin tests cannot be performed.
C 616	04		peed Control for LN pump			Safe	OK - power can be removed at local fuse panel if required. Co
C 610	04	_	peed Control for LN pump	Fails On or too fast	No Hazard		tests cannot be performed.
			-				
SSUF	relie			Fails open	High boil off rate	Safe	Operational problem - boiloff vents thru SV-6213. Liquid loss withigh and cooling tests will not be possible to perform.
SV 616	00		acuum positive pressure relief on reservoir vacuum jacket				OK - Requires double failure, vacuum pumpout port associated
SV 611	00	V	facium positive pressure relief on reservoir vacuum jacket	Fails closed	Vacuum space not adequately relieved.	Safe	VV-6105 will provide some relief capacity.  Operational problem - If MV-6204 is open or the filling process.
SV 62	00	LN2	ill port, trapped volume relief	Fails open	Dewar blows down	Safe	lunderway LN2 will spill onto the ground outside Lab A.
- 102	-						OK - Low probability of a quality Circle-Seal relief valve failing completely shut. As pressure in the trapped volume exceeded:
SV 62	000	LN2	Fill port, trapped volume relief	Fails closed	Trapped volume not relieved	Safe	relief valve set point, the probability of a stuck relief valve oper would increase. All trapped volume reliefs were tested by Femprior to installation.
_	-		The state of the s	Fails open	Dewar blows down	Safe	Operational problem - can't perform cooling tests.
SV 62	213		Reservoir Positive pressure main relief	Fails closed	No Hazard	Safe	OK - Dewar will vent thru RD-6214 if necessary.
SV 62	213	LN2	Reservoir Positive pressure main relief			Safe	Operational problem - Can't measure heat leak thru FI-6201.
SV 62	218	LN2	Trapped volume relief for FI 6201	Fails open	No Hazard	Sale	OK - Low probability of a quality Circle-Seal relief valve failing
SV 62	218	LN2	Trapped volume relief for FI 6201	Fails closed	FI-6201 is over pressurized	Safe	completely shut. As pressure in the trapped volume exceeded reser valve set point, the probability of a stuck reiser valve oper would increase. All trapped volume reliefs were tested by Ferr prior to installation.
_	4					0-1-	Operational problem - Liquid would be pumped out the relief an
SV 63	304	LN2	Return line, trapped volume relief near reservoir	Fails open	Dewar blows down, pumped liquid lost	Safe	system would depressurize. Cooling tests could not be perfor
SV 63	304	LN2	Return line, trapped volume reflet near reservoir	Fails closed	Trapped volume not relieved	Safe	OK - Low probability of a quality Circle-Saal relef valve failing completely slut. As pressure in the trapped volume exceeded relef valve set point, the probability of a stuck relef valve one would increase. All trapped volume relefs were tested by Fen prior to installation.
CV 4	208	LN2	Supply line transed volume relief near reservoir	Fails open	Dewar blows down, pumped liquid lost	Safe	Operational problem - Liquid would be pumped out the relief are system would depressurize. Cooling tests could not be perform
SV 6	JJ0	LINZ	Supply line trapped volume relief near reservoir	<u> </u>			OK - Low probability of a quality Circle-Seal relief valve failing
		LN2	Supply line trapped volume relief near reservoir	Fails closed	Trapped volume not relieved	Safe	completely shul. As pressure in the trapped volume exceeded relief valve set point, the probability of a stuck relief valve ope would increase. All trapped volume reliefs were tested by Fer prior to installation.
SV 6	306					Safe	Operational problem - Liquid would be pumped out the relief a
		1,1.00		Fails open	Dewar blows down, pumped liquid lost		system would depressurize. Cooling tests could not be benor
	306	LN2	Supply line trapped volume relief reservoir check valve	Fails open	Dewar blows down, pumped iiquid lost		OK -Low probability of a quality Circle-Seal relief valve falling
SV 6		_	Supply line trapped volume relief reservoir check valve	Fails open	Dewar blows down, pumper inquire lost	Safe	system would depressuitze. Cooling tests could not be perfor OK - Low probability of a quality Circle-Seal relief valve failing completely shut. As pressure in the trapped volume exceeded relief valve set point, the probability of a stuck relief valve ope would increase. All trapped volume reliefs were tested by Fer prior to installation.
sv 6	311	_					OK -Low probability of a quality Circle-Seal relief valve falling completely shut. As pressure in the trapped volume exceeds relief valve set point, the probability of a stuck relief valve op- would increase. All trapped volume reliefs were tested by Fe
SV 6	311	LN2	Supply line trapped volume relief reservoir check valve	Falls closed	Trapped volume not relieved	Safe	OK - Low probability of a quality Circle-Seal relief valve failing completely shuf. As pressure in the trapped volume exceeder relefer valve set point, the probability of a stuck relief valve set point, the probability of a stuck relief valve polywould increase. All trapped volume reliefs were tested by Perprior to installation.
SV 6	311	LN2	Supply line trapped volume relief reservoir check valve		Trapped volume not relieved	Safe Safe	OK - Low probability of a quality Circle-Seal relief valve failing completely shuf. As pressure in the trapped volume exceeder relefer valve set point, the probability of a stuck relief valve open would increase. All trapped volume reliefs were tested by Ferpiror to installation.  Operational problem - Heat leak calculations will be inaccurated.
SV 6	311	LN2	Supply line trapped volume relief reservoir check valve	Falls closed	Trapped volume not refleved  Cryocooler performance misrepresented	Safe	OK - Low probability of a quality Circle-Seal relief valve failing completely shuf. As pressure in the trapped volume exceeder relief valve set point, the probability of a stuck relief valve set point, the probability of a stuck relief valve powould increase. All trapped volume reliefs were tested by Perpiror to installation.  Operational problem - Heat leak calculations will be inaccurated operational problem - Heat leak calculations will be inaccurated.
SV 6	3311 3311 3311 3210	LN2	Supply line trapped volume relief reservoir check valve	Fails closed  Incorrect reading - low	Trapped volume not refleved  Cryocooler performance misrepresented  Cryocooler performance misrepresented	Safe Safe	OK - Low probability of a quality Circle-Seal relief valve failing completely shuf. As pressure in the trapped volume exceeds relief valve set point, the probability of a stuck relief valve operations. At trapped volume reliefs were tested by Fe prior to installation.  Operational problem - Heat leak calculations will be inaccurat Operational problem - Heat leak calculations will be inaccurat Operational problem - Heat leak calculations will be inaccurat Heat end (accordance).
SV 6	3311 3311 3311 3210 3210	LN2 elen N2 N2 N2	Supply line trapped volume relief reservoir check valve  entis  Temperature Element, Condenser Temperature  Temperature Element, Condenser Temperature  Temperature Element, Condenser Temperature	Falls closed  Incorrect reading - low Incorrect reading - high Incorrect reading - low	Trapped volume not relieved  Cryocooler performance misrepresented Cooling performance misrepresented	Safe Safe Safe	OK - Low probability of a quality Circle-Seal relief valve felling completely shut. As pressure in the trapped volume exceeder relief valve set point, the probability of a shuck relief valve op would increase. All trapped volume reliefs were tested by Forpiror to installation.  Operational problem - Heat leak calculations will be inaccurat Operational problem - Heat leak calculations will be inaccurat Operational problem - Heat leak calculations will be inaccurat Heater 6102 protected with thermal switch set at 550. Operational problem - Heat leak calculations will be inaccurated that the control of the calculations will be inaccurated to the calculations will be inaccurated as the calculations will be calculated as the calculation
SV 6	3311 3311 3311 3210	LN2	Supply line trapped volume relief reservoir check valve  STATE  Temperature Element, Condenser Temperature  Temperature Element, Condenser Temperature  Temperature element, Condenser Temperature  Temperature element, Top Reservoir Gas Temperature  Temperature element, Top Reservoir Gas Temperature	Fails closed  Incorrect reading - low Incorrect reading - low Incorrect reading - low Incorrect reading - low	Trapped volume not relieved  Cryocooler performance misrepresented Cooling performance misrepresented Cooling performance misrepresented	Safe Safe Safe Safe Safe	OK - Low probability of a quality Circle-Seal relief valve failing completely shuf. As pressure in the trapped volume exceeder relevative set point, the probability of a stuck relief valve set point, the probability of a stuck relief valve opwould increase. All trapped volume reliefs were tested by Fe prior to installation.  Operational problem - Heat leak calculations will be inaccurated to the problem - Heat leak calcula
SSV 6	3311 3311 3311 3210 3210	LN2 elem N2 N2 N2 N2	Supply line trapped volume relief reservoir check valve  entis  Temperature Element, Condenser Temperature  Temperature Element, Condenser Temperature  Temperature Element, Condenser Temperature	Falls closed  Incorrect reading - low Incorrect reading - high Incorrect reading - low	Trapped volume not relieved  Cryocooler performance misrepresented Cryocooler performance misrepresented Cooling performance misrepresented Cooling performance misrepresented Cooling performance misrepresented	Safe Safe Safe Safe Safe Safe	OK - Low probability of a quality Circle-Seal relief valve failing completely shut. As pressure in the trapped volume exceeder relief valve set point, the probability of a stuck relief valve operations of the property of t
SV 6	3311 3311 3210 3210 3211	LN2 elem N2 N2 N2 N2	Supply line trapped volume relief reservoir check valve  STATE  Temperature Element, Condenser Temperature  Temperature Element, Condenser Temperature  Temperature element, Condenser Temperature  Temperature element, Top Reservoir Gas Temperature  Temperature element, Top Reservoir Gas Temperature	Fails closed  Incorrect reading - low Incorrect reading - low Incorrect reading - low Incorrect reading - low	Trapped volume not relieved  Cryocooler performance misrepresented Cooling performance misrepresented Cooling performance misrepresented Cooling performance misrepresented Cooling performance misrepresented	Safe Safe Safe Safe Safe	OK - Low probability of a quality Circle-Seal relief valve failing completely shut. As pressure in the trapped volume exceede relief valve set point, the probability of a stuck relief valve powdid increase. All trapped volume reliefs were tested by Fe prior to installation.  Operational problem - Heat leak calculations will be inaccural Operational problem - Heat leak calculations will be inaccural Operational problem - Heat leak calculations will be inaccural Operational problem - Heat leak calculations will be inaccural Heater 6102 protected with thermal swich, set at 55 C. Operational problem - Heat leak calculations will be inaccural Operational problem - Heat leak calculations will be inaccural Operational problem - Heat leak calculations will be inaccural Operational problem - Heat leak calculations will be inaccural Operational problem - Heat leak calculations will be inaccural Operational problem - Heat leak calculations will be inaccural Operational problem - Heat leak calculations will be inaccural Operational problem - Heat leak calculations will be inaccural Operational problem - Heat leak calculations will be inaccural Operational problem - Heat leak calculations will be inaccural Operational problem - Heat leak calculations will be inaccural Operational problem - Heat leak calculations will be inaccural Operational problem - Heat leak calculations will be inaccural Operational problem - Heat leak calculations will be inaccural Operational problem - Heat leak calculations will be inaccural Operational problem - Heat leak calculations will be inaccural Operational Problem - Heat leak calculations will be inaccural Operational Problem - Heat leak calculations will be inaccural Operational Problem - Heat leak calculations will be inaccural Operational Problem - Heat leak Calculations will be inaccural Operational Problem - Heat leak Calculations will be inaccural Operational Problem - Heat leak Calculations will be inaccural Operational Problem - Heat leak Calculations will be inaccural Operational Pr
SV 6	3311 3311 3311 3210 3210 3211 5403 6403	N2 N2 N2 N2 N2 N2 N2	Supply line trapped volume relief reservoir check valve  SILLS  Temperature Element, Condenser Temperature  Temperature Element, Condenser Temperature  Temperature element, Top Reservoir Gas Temperature  Temperature element, Top Reservoir Gas Temperature  Return line, Temperature indicator near heat exchanger  Return line, Temperature indicator near heat exchanger	Incorrect reading - low	Trapped volume not relieved  Cryocooler performance misrepresented Cryocooler performance misrepresented Cooling performance misrepresented Cooling performance misrepresented Cooling performance misrepresented Cooling performance misrepresented	Safe Safe Safe Safe Safe Safe	OK - Low probability of a quality Circle-Seal relief valve felling completely shut. As pressure in the trapped volume exceeder relief valve set point, the probability of a shuck relief valve set point, the probability of a shuck relief valve op would increase. All trapped volume reliefs were tested by Fe prior to installation.  Operational problem - Heat leak calculations will be inaccural Coperational problem - Heat leak calculations will be inaccural thater 6102 protected with thermal switch set at 550. Operational problem - Heat leak calculations will be inaccural Heater 6102 protected with thermal exitch switch set at 550. Operational problem - Heat leak calculations will be inaccural Heater 6102 protected with thermal exitch switch is the inaccural Operational problem - Heat leak calculations will be inaccural Operational problem - Heat leak calculations will be inaccural Operational problem - Heat leak calculations will be inaccural operational problem - Heat leak calculations will be inaccural operational problem - Heat leak calculations will be inaccural operational problem - Heat leak calculations will be inaccural operational problem - Heat leak calculations will be inaccural operational problem - Heat leak calculations will be inaccural operational problem - Heat leak calculations will be inaccurally operational problem - Heat leak calculations will be inaccurally operational problem - Heat leak calculations will be inaccurally operational problem - Heat leak calculations will be inaccurally operational problem - Heat leak calculations will be inaccurally operational problem - Heat leak calculations will be inaccurally operations ope
SV 6: SV 6: SV 6: TE 6: TE 6: TE 6: TE 6: TE 6: TE 6:	3311 3311 3311 3210 3210 3211 5403 6403	N2 N2 N2 N2 N2 N2 N2	Supply line trapped volume relief reservoir check valve  STATE  Temperature Element, Condenser Temperature  Temperature Element, Condenser Temperature  Temperature element, Top Reservoir Gas Temperature  Temperature element, Top Reservoir Gas Temperature  Temperature element, Top Reservoir Gas Temperature  Return line, Temperature indicator near heat exchanger  Return line, Temperature indicator near heat exchanger  Supply line, Temperature indicator near heat exchanger	Incorrect reading - low	Trapped volume not relieved  Cryocooler performance misrepresented Cryocooler performance misrepresented Cooling performance misrepresented	Safe Safe Safe Safe Safe Safe Safe Safe	OK - Low probability of a quality Circle-Seal relief valve failing completely shut. As pressure in the trapped volume exceeder relief valve set point, the probability of a struck relief valve op would increase. All trapped volume reliefs were tested by Fe prior to installation.  Operational problem - Heat leak calculations will be inaccural Operational problem - Heat leak calculations will be inaccural Operational problem - Heat leak calculations will be inaccural Operational problem - Heat leak calculations will be inaccural Operational problem - Heat leak calculations will be inaccural Operational problem - Heat leak calculations will be inaccural Operational problem - Heat leak calculations will be inaccural Operational problem - Heat leak calculations will be inaccural Operational problem - Heat leak calculations will be inaccural Heater 6102 protected with thermal switch set 45 5C.  Operational problem - Heat leak calculations will be inaccural operational problem - Heat leak calculations will be inaccural problem - Heat leak calculations will be inaccurally the state of the calculations of the inaccural problem - Heat leak calculations will be inaccurally on the state of the calculations will be inaccurally only the state of the calculations of the inaccural problem - Heat leak calculations will be inaccurally only the state of the calculations will be inaccurally only the state of the calculations will be inaccurally only the state of the calculations will be inaccurally only the state of the calculations will be inaccurally only the state of the calculations will be inaccurally only the state of the calculations will be inaccurally only the state of the calculations will be inaccurally only the state of the calculations will be inaccurally only the state of the calculations will be inaccurally only the state of the calculations will be inaccurally only the state of the calculations will be inaccurally only the state of the calculations will be inaccurally only the state of the calculations will be inacu
SV 6: SV 6: SV 6: TE 6: TE 6: TE 6: TE 6: TE 6: TE 6:	3311 3311 3311 3210 3210 3211 5403 6403	N2 N2 N2 N2 N2 N2 N2	Supply line trapped volume relief reservoir check valve  SILLS  Temperature Element, Condenser Temperature  Temperature Element, Condenser Temperature  Temperature element, Top Reservoir Gas Temperature  Temperature element, Top Reservoir Gas Temperature  Return line, Temperature indicator near heat exchanger  Return line, Temperature indicator near heat exchanger	Incorrect reading - low	Trapped volume not relieved  Cryocooler performance misrepresented Cryocooler performance misrepresented Cooling performance misrepresented	Safe Safe Safe Safe Safe Safe Safe Safe	OK - Low probability of a quality Circle-Seal relief valve felling completely shut. As pressure in the trapped volume exceeder relief valve set point, the probability of a shuck relief valve set point, the probability of a shuck relief valve op would increase. All trapped volume reliefs were tested by Fe prior to installation.  Operational problem - Heat leak calculations will be inaccural Coperational problem - Heat leak calculations will be inaccural thater 6102 protected with thermal switch set at 550. Operational problem - Heat leak calculations will be inaccural Heater 6102 protected with thermal exitch switch set at 550. Operational problem - Heat leak calculations will be inaccural Heater 6102 protected with thermal exitch switch is the inaccural Operational problem - Heat leak calculations will be inaccural Operational problem - Heat leak calculations will be inaccural Operational problem - Heat leak calculations will be inaccural operational problem - Heat leak calculations will be inaccural operational problem - Heat leak calculations will be inaccural operational problem - Heat leak calculations will be inaccural operational problem - Heat leak calculations will be inaccural operational problem - Heat leak calculations will be inaccural operational problem - Heat leak calculations will be inaccurally operational problem - Heat leak calculations will be inaccurally operational problem - Heat leak calculations will be inaccurally operational problem - Heat leak calculations will be inaccurally operational problem - Heat leak calculations will be inaccurally operational problem - Heat leak calculations will be inaccurally operations ope
SV 6: SV 6: SV 6: TE 6:	3311 3311 3210 3210 3211 5403 8404 8404	N2 N2 N2 N2 N2 N2 N2 N2 N2	Supply line trapped volume relief reservoir check valve  entits  Temperature Element, Condenser Temperature  Temperature Element, Condenser Temperature  Temperature element, Top Reservoir Gas Temperature  Temperature element, Top Reservoir Gas Temperature  Temperature element, Top Reservoir Gas Temperature  Return line, Temperature indicator near heat exchanger  Supply line, Temperature indicator near heat exchanger  Supply line, Temperature indicator near heat exchanger	Incorrect reading - low	Trapped volume not relieved  Cryocooler performance misrepresented Cryocooler performance misrepresented Cooling performance misrepresented	Safe Safe Safe Safe Safe Safe Safe Safe	OK -Low probability of a quality Circle-Seal relief valve felling completely shut. As pressure in the trapped volume exceeder relief valve set point, the probability of a stuck relief valve op would increase. All trapped volume reliefs were tested by Fe prior to installation.  Operational problem - Heat leak calculations will be inaccural Operational problem - Heat leak calculations will be inaccural Operational problem - Heat leak calculations will be inaccural Heater 6102 protected with thermal switch set at 55C. Operational problem - Heat leak calculations will be inaccural Heater 6102 protected with thermal switch set at 55C. Operational problem - Heat leak calculations will be inaccural Compositional problem - Heat leak calculations will be inaccural Compositional problem - Heat leak calculations will be inaccural Compositional problem - Heat leak calculations will be inaccural Heater 6102 protected with thermal switch set at 55C. Operational problem - Heat leak calculations will be inaccural Heater 6102 protected with thermal switch set at 55C. Operational problem - Heat leak calculations will be inaccural Heater 6102 protected with thermal switch set at 55C.
SV 6	3311 3311 3311 3210 3210 3211 5403 6403 6404	N2 N2 N2 N2 N2 N2 N2 N2 N2	Supply line trapped volume relief reservoir check valve  Temperature Element, Condenser Temperature  Temperature Element, Condenser Temperature  Temperature element, Top Reservoir Gas Temperature  Temperature element, Top Reservoir Gas Temperature  Return line, Temperature indicator near heat exchanger  Supply line, Temperature indicator near heat exchanger  Supply line, Temperature indicator near heat exchanger	Incorrect reading - low	Trapped volume not relieved  Cryocooler performance misrepresented Cryocooler performance misrepresented Cooling performance misrepresented	Safe Safe Safe Safe Safe Safe Safe Safe	OK - Low probability of a quality Circle-Seal relief valve failing completely shul. As pressure in the trapped volume exceeder relet valve set point, the probability of a stuck relief valve oper would increase. All trapped volume reliefs were tested by Fer prior to installation.  Operational problem - Heat leak calculations will be inaccurated to the problem of th
SV 65 SV 65 SV 65 TE 65 TE 65 TE 67	3311 3311 3210 3210 3211 5403 8404 8404	LN2 stem N2 N2 N2 N2 N2 N2 N2 N2 V	Supply line trapped volume relief reservoir check valve  entits  Temperature Element, Condenser Temperature  Temperature Element, Condenser Temperature  Temperature element, Top Reservoir Gas Temperature  Temperature element, Top Reservoir Gas Temperature  Temperature element, Top Reservoir Gas Temperature  Return line, Temperature indicator near heat exchanger  Supply line, Temperature indicator near heat exchanger  Supply line, Temperature indicator near heat exchanger	Incorrect reading - low	Trapped volume not relieved  Cryocooler performance misrepresented Cryocooler performance misrepresented Cooling performance misrepresented	Safe Safe Safe Safe Safe Safe Safe Safe	OK - Low probability of a quality Circle-Seal relief valve felling completely shut. As pressure in the trapped volume exceeder relief valve set point, the probability of a stuck relief valve set point, the probability of a stuck relief valve op would increase. All trapped volume reliefs were tested by Fe prior to installation.  Operational problem - Heat leak calculations will be inaccural Operational problem - Heat leak calculations will be inaccural Heater 6102 protected with thermal switch set at 550. Operational problem - Heat leak calculations will be inaccural Heater 6102 protected with thermal switch set at 550. Operational problem - Heat leak calculations will be inaccural Heater 6102 protected with thermal switch set at 550. Operational problem - Heat leak calculations will be inaccural operational problem - Heat leak calculations will be inaccural tested to the set of
SV 6: SV 6: SV 6: TE 7: TE 6: TE 7: TE 6: TE 7:	3311 3311 3311 3210 3210 3211 5211 5403 6404 6105	LN2 stem N2 N2 N2 N2 N2 N2 N2 N2 V	Supply line trapped volume relief reservoir check valve  strike  Temperature Element, Condenser Temperature  Temperature Element, Condenser Temperature  Temperature element, Top Reservoir Gas Temperature  Temperature element, Top Reservoir Gas Temperature  Temperature element, Top Reservoir Gas Temperature  Return line, Temperature indicator near heat exchanger  Supply line, Temperature indicator near heat exchanger  Supply line, Temperature indicator near heat exchanger	Incorrect reading - low	Trapped volume not relieved  Cryocooler performance misrepresented Cryocooler performance misrepresented Cooling performance misrepresented High boil off rate	Safe Safe Safe Safe Safe Safe Safe Safe	OK - Low probability of a quality Circle-Seal relief valve telling completely shul. As pressure in the trapped volume exceeder relief valve set point, the probability of a shuck relief valve set point, the probability of a shuck relief valve op would increase. All trapped volume reliefs were tested by Fe prior to installation.  Operational problem - Heat leak calculations will be inaccural Operational problem - Heat leak calculations will be inaccural Heater 6102 protected with thermal switch set at 55C. Operational problem - Heat leak calculations will be inaccural Heater 6102 protected with thermal switch set at 55C. Operational problem - Heat leak calculations will be inaccural Operational problem - Heat leak calculations will be inaccural Operational problem - Heat leak calculations will be inaccural Operational problem - Heat leak calculations will be inaccural Operational problem - Heat leak calculations will be inaccural Operational problem - Heat leak calculations will be inaccural Operational problem - Heat leak calculations will be inaccural Operational problem - Heat leak calculations will be inaccural Operational problem - Heat leak calculations will be inaccural Heater 6102 protected with thermal switch set at 55C.  Operational problem - Heat leak calculations will be inaccural Heater 6102 protected with thermal switch set at 55C.  Operational problem - Heat leak calculations will be inaccural Heater 6102 protected with thermal switch set at 55C.
SV 6: SV 6: SV 6: TE 6: TE 6: TE 6: TE 6: TE 6: W 1: Acceptain	3311 3311 3210 3210 3211 5211 5211 5403 6403 6404 6105	N2 N	Supply line trapped volume relief reservoir check valve  strike  Temperature Element, Condenser Temperature  Temperature Element, Condenser Temperature  Temperature element, Top Reservoir Gas Temperature  Temperature element, Top Reservoir Gas Temperature  Temperature element, Top Reservoir Gas Temperature  Return line, Temperature indicator near heat exchanger  Supply line, Temperature indicator near heat exchanger  Supply line, Temperature indicator near heat exchanger	Incorrect reading - low	Trapped volume not relieved  Cryocooler performance misrepresented Cryocooler performance misrepresented Cooling performance misrepresented High boil off rate Vacuum space pressure can't be lowered	Safe Safe Safe Safe Safe Safe Safe Safe	OK - Low probability of a quality Circle-Seal relief valve falling completely shul. A pressure in the trapped volume exceeder relief valve set point, the probability of a stuck relief valve open would increase. All trapped volume reliefs were tested by Fermior to installation.  Operational problem - Heat leak calculations will be inaccurat Operational problem - Heat leak calculations will be inaccurat Operational problem - Heat leak calculations will be inaccurat Operational problem - Heat leak calculations will be inaccurat Operational problem - Heat leak calculations will be inaccurat Heater 6102 protected with thermal switch set at 55C.  Operational problem - Heat leak calculations will be inaccurat Operational problem - Heat leak calculations will be inaccurat Operational problem - Heat leak calculations will be inaccurat Operational problem - Heat leak calculations will be inaccurat Operational problem - Heat leak calculations will be inaccurat Heater 6102 protected with thermal switch set at 55C.  Operational problem - Heat leak calculations will be inaccurat Heater 6102 protected with thermal switch set at 55C.  Operational problem - Heat leak calculations will be inaccurat Heater 6102 protected with thermal switch set at 55C.